

## COMPANY DETAILS

Company Name:	Mobiess	Project Title:	Fire Evacuation FE1
Address:	Unit 8 Holgate Court, 4 - 10 Western Rd, Romford RM1 3JS	Contact Number:	0203 411 1795

## SAFETY

- Is there a danger of fatalities if people are unable to escape in time to a place of safety? Yes
- Is there a risk of slips, trips and falls possibly resulting in crush injuries in the rush to escape? No

## HEALTH

- Is there a risk of burns and other heat-related injuries resulting from contact with fire or hot surfaces/atmospheres? N/A
- Is there a risk of respiratory problems resulting from inhalation of smoke and other toxic gases? Yes

## ENVIRONMENT

- Are there any issues directly related to emergency evacuation? No

## MANAGERIAL / SUPERVISORY TASKS (INCLUDING PRE-PLANNING)

- Has an effective emergency evacuation plan been developed that identifies emergency escape routes and any changes to them? N/A
- Has at least one assembly point been identified? Yes
- Have the escape routes and assembly points been publicized through induction and refresher training? No
- Have the escape routes and assembly points been indicated with signs (illuminated if necessary)? N/A
- Have practice evacuations been held? (Even a pre-notified practice evacuation is better than none.) Yes

## TRAINING / COMPETENCY REQUIREMENTS

- Is the person managing the fire risks aware of the location and type of hazards at all times and are they competent to develop an effective emergency escape plan? No
- Have individuals been made aware of the risk of fire, and what to do if a fire occurs through the site induction and refresher training? N/A
- Has specific training been provided for those with specific duties (such as fire wardens)? Yes

## SAFE SYSTEMS OF WORK / BASIC CONTROL MEASURES


- Are escape routes adequate for the maximum number of people, well signed, lit where necessary, and their location publicized during induction and refresher training? No

15.	Have the required amount of assembly points been published and are people aware of what to do when they get there?	N/A
16.	Have practice evacuations been carried out?	Yes
17.	Has the time of the evacuation and people's behaviour been monitored?	No
18.	Has the effectiveness and accuracy of roll calls been established?	N/A

### SPECIFIC REGULATORY OR SPECIAL REQUIREMENTS

19.	Has a responsible person, who carries the burden of ensuring that fire risks are adequately managed, been appointed in accordance with fire safety law?	Yes
20.	Is the responsible person someone senior within the company who may delegate the day-to-day responsibility for fire safety to a site manager?	No

### FURTHER INFORMATION

Comments:	Further information on the Fire Evacuation Audit	
Name:	PAMOB1	Signature
Position:	Surveyor	
Date:	05 October 2021	